



EXECUTIVE ENGINEER, PUBLIC WORKS DEPARTMENT DEVISION,VIJAYAPUR-586128

Telephone : 08352250045

Fax : 08352251062

Email: eepwdbjp062@rediffmail.com

Ref: PWD/VV/PB/AE-1/2021-22/1155

Date : 29-07-2021

To,
The principal
Loyola School (CBSE)
Jewargi Road
Sindagi,
Dst. Vijayapura

Sir,

Sub: Building safety certificate of 'Loyola School(CBSE)' Sindagi

Ref : 1) Principal Loyola School (CBSE) Sindagi , Letter dated : 15-07-2021

2) Asst. Executive engineer , PWD subdivision Sindagi, Letter no 163 date : 28-07-2021

After the inspection of the building documents and the certificate of structural stability issued by the engineer of Review multi consultancy engineer , the assistant Executive engineer , PWD subdivision Sindagi has certified that the "Loyola school(CBSE)" building is structurally safe for the school building.


The building safety certificate has been attached with this document.

Enclosed: Building safe certificate -1

Your faithfully,

sd

Executive Engineer,
Public Works Department
Vijayapur Division



D:/Bani AE/Letter to Principal Loyola School Sindagi.doc

ATTESTED BY ME

A. K. KANNUR B.A., LL.B. (Spr)
Advocate & Notary, Govt. of India
At: Po. SINDAGI-586128
Sindagi Dt: Vijayapur Mob: 9845898579

Building safety certificate

28-07-2021


This is to certify that the “**Loyola School**” building survey no: 243/3 located at Sindagi town Vijayapura District is structurally safe for the School building. The inspection has been conducted based on the structural analysis certification report and the documents sent by ‘review multi consultancy’. Based on this we certify that the Loyola school building is structurally safe.

Sd
Asst. Executive Engineer
Public Works Sub-Department
Sindagi

Sd
Executive Engineer
Public Works Department
Vijayapur Division



ATTESTED BY ME


A. K. KANNUR B.Sc., B.L., (Spr)
Advocate & Notary, Govt. of India
At: Po. SINDAGI-586128
Sindagi, Dt: Vijayapur Mob: 9845898578



ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ವಿಭಾಗ, ವಿಜಯಪುರ - ೫೮೬ ೧೦೧
EXECUTIVE ENGINEER, PUBLIC WORKS DEPARTMENT DEVISION, VIJAYAPUR - 586 101

ದೂರವಾಣಿ : } 08352 250045

Telephone: } 08352 251062 (Fax)

Email: eepwdbjp062@rediffmail.com

ಕ್ರ:ಲೋಇ/ವಿವಿ/ಪಿಬಿ/ಎಇ-1/2021-22/

ದಿನಾಂಕ: 29-7-2021

1155

ಗೆ,

ಪ್ರಾಚಾರ್ಯರು,

ಲೋಯೋಲಾ ಶಾಲೆ (ಸಿಬಿಎಸ್‌ಇ),

ಚೇವರ್ಗಿ ರಸ್ತೆ,

ಸಿಂದಗಿ.

ಜಿ: ವಿಜಯಪುರ.

ಮಾನ್ಯರೆ,


ವಿಷಯ:- ಸಿಂದಗಿಯಲ್ಲಿರುವ ಲೋಯೋಲಾ ಶಾಲಾ (ಸಿಬಿಎಸ್‌ಇ) ಕಟ್ಟಡ ಸುರಕ್ಷತೆ ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ:-
- 1) Principal, Loyola School (CBSE) Sindagi ಇವರ ಪತ್ರ ದಿನಾಂಕ: 15-07-2021.
 - 2) ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರರು ಲೋಇ ಉಪ ವಿಭಾಗ ಸಿಂದಗಿ ಇವರ ಪತ್ರ ಸಂ. 163 ದಿನಾಂಕ: 28-07-2021.

ಮೇಲ್ಕಾಣಿಸಿದ ವಿಷಯ ಹಾಗೂ ಉಲ್ಲೇಖಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಿಂದಗಿಯಲ್ಲಿರುವ ಲೋಯೋಲಾ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆವಾಗಿರುತ್ತದೆ ಎಂದು ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರರು ಲೋಇ ಉಪ ವಿಭಾಗ ಸಿಂದಗಿ ಇವರು ವರದಿಸಿರುತ್ತಾರೆ. ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರರು ಲೋಇ ಸಿಂದಗಿ ಇವರು ಸದರಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆ (Structural Stability Certificate) ಅನ್ನು Review Multi Consultancy ಇಂಜಿನಿಯರ ಇವರು ನೀಡಿದ ಸುರಕ್ಷತೆ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಆಧರಿಸಿ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ. ಸದರಿ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಈ ಪತ್ರಕ್ಕೆ ಲಗತ್ತಿಸಿ ತಮಗೆ ಈ ಮೂಲಕ ಕಳುಹಿಸಲಾಗಿದೆ.


ಅಡಕ: ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ-1


ತಮ್ಮ ವಿಶ್ವಾಸಿಕ,


ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರರು
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ವಿಭಾಗ, ವಿಜಯಪುರ.

ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ

ವಿಜಯಪುರ ಜಿಲ್ಲೆಯ ಸಿಂದಗಿ ಪಟ್ಟಣದ ಸರ್ವೆ ನಂ: 243/3 ರಲ್ಲಿ ನಿರ್ಮಿಸಲಾದ "ಲೋಯೋಲಾ ಸ್ಕೂಲ್"ನ ಕಟ್ಟಡದ Structural Analysis ವರದಿಯನ್ನು Review Multi Consultancy, ವಿಜಯಪುರ ಇವರು ನೀಡಿದ್ದು, ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದೆ ಎಂದು ವರದಿಸಿರುತ್ತಾರೆ. ಈ ವರದಿಯನ್ನು ಆದರಿಸಿ ಲೋಯೋಲಾ ಸ್ಕೂಲ್‌ನ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದೆ ಎಂದು ಪ್ರಮಾಣೀಕರಿಸಲಾಗಿದೆ.


ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ ವಿಭಾಗ,
ಸಿಂದಗಿ.


ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ವಿಭಾಗ,
ವಿಜಯಪುರ.